

Construction update of
Botanica-9th
October, 2025
PHASE-II

1.Cluster-06, Unit no. 190 to 203

- ☐ Pile works is completed.
- ☐ Sub structure is in progress.

2.Cluster-07, Unit no. 184 to 189

- ☐ Pile works is completed.
- ☐ Sub structure works is in progress.

3.Cluster-8, Unit no. 181 TO 183

- ☐ Pile works is completed.
- ☐ Sub structure works is in progress.

4.Cluster-9, Unit no. 175 TO 180

- ☐ Pile works is completed.
- ☐ Sub structure works is in progress.

5.Cluster-13, Unit no. 131 To 151 & 212

- ☐ Pile works is completed

6.Cluster-15, Unit no. 122 to 126

Civil sub structure work is completed.(122 to 126)

- ☐ Ground floor slab completed. (122 to 126)
- ☐ 1st floor slab is completed.(122 to 126)
- ☐ Brick Work is in progress.
- ☐ Roof slab is completed.
- ☐ Plaster work is in progress.

7.Cluster-23, Unit no. 174

- ☐ Civil sub structure work is completed.
- ☐ Ground floor slab is completed.
- ☐ 1st floor slab is completed.

- ☐ Roof slab is completed.
- ☐ Brick work is Done.
- ☐ Electrical work is in progress.
- ☐ Plaster work is in progress.
- ☐ Plumbing work is in progress.
- ☐ Waterproofing work is in progress.
- ☐ Flooring work is in progress.
- ☐ External paint is in progress.

8.Cluster-24, Unit no. 158 TO 162

- ☐ Pile works is completed.

9.Cluster-25, Unit no. 163 TO 167

- ☐ Pile works is completed.
- ☐ Sub-structure is in progress.

10.Cluster-29,Unit no. 106 TO 109

- ☐ Pile works is completed.
- ☐ Sub structure work is completed.
- ☐ Ground floor slab completed.
- ☐ 1st floor slab is completed.(106 to 109)
- ☐ Brick work is in progress.
- ☐ Roof slab is completed.
- ☐ Plaster work is in progress.

11.Cluster-32,Unit no. 115 TO 118

- ☐ Sub structure is completed.
- ☐ Ground floor slab is completed.
- ☐ 1st floor slab is completed.
- ☐ Roof slab is completed.
- ☐ Brick work is in progress.
- ☐ Electrical work is in progress.
- ☐ Plaster work is in progress.

12.Cluster-5,Unit no. 204 TO 211

- ☐ Pile works is completed.
- ☐ Sub structure is in progress.

13.Cluster-30,Unit no. 110 TO 111

- ☐ Civil sub structure work completed.
- ☐ Ground floor slab is completed.
- ☐ 1st floor slab is completed.
- ☐ Brick work is started.
- ☐ Roof slab is completed.
- ☐ Plaster work is in progress.
- ☐ External paint work is in progress.

14.Cluster-33,Unit no. 119 TO 121

- ☐ Civil sub structure work is in progress.
- ☐ Ground floor slab is completed.
- ☐ 1st floor slab is completed.
- ☐ Brickwork is in progress.
- ☐ Roof slab is completed.

15.Cluster-31,Unit no. 112 TO 114

- ☐ Civil sub structure work is in progress.
- ☐ Ground floor slab is completed.
- ☐ 1st floor slab is completed.
- ☐ Brickwork is in progress.
- ☐ Roof slab is completed.

16.Cluster-28,Unit no. 100 TO 105

- ☐ Pile work is completed.
- ☐ Sub structure is in progress.

18.Cluster-26,Unit no. 168 TO 173

- ☐ Pile work is completed.
- ☐ Sub structure is in progress.

19.Cluster-27,Unit no. 152 TO 157

- ☐ Pile work is completed.

20.Cluster-14,Unit no. 127 TO 136

- Civil sub structure work is in progress(132 to 134).

CLUB:

- Piling Completed.
- Excavation work in completed.
- Raft Completed.
- Retaining Wall completed.
- Ground floor slab completed .
- 1st floor slab is completed.
- Brick work is in progress.
- 2nd floor slab is completed.
- Plaster work is in progress.
- Roof slab is completed.
- POP work is in progress.
- Aluminium work is in progress.
- Fire work is in progress.
- Waterproofing work is in progress.
- Electrical work is in progress.
- Plumbing work is in progress.
- Flooring work is in progress.
- Internal paint work is in progress.
- External paint work is in progress.

ROAD

- Flooring work of road is completed at cl-3&4 ,cl-17&19, cl-15&33, cl-20&21, 22&23,31&32,29&30.
- Landscape work is completed.
- Road Flooring work is in progress in front of club.