

Devashilpi-Ekam (Phase-1) Tower-3, Work Progress As On 30-09-2025

TASK	STATUS	COMPLETION %
CIVIL WORK		
Excavation Work	Done	100%
Footing Work	Done	100%
Column Upto Plinth	Done	100%
Backfilling In Footing	Done	100%
Plinth Beam	Done	100%
Earth Filling In Plinth	Done	100%
Anti Termite Treatment	Done	100%
Ground Floor Slab Casting	Done	100%
Column Ground Floor to 1st Floor	Done	100%
1st Floor Slab Casting	Done	100%
Ground Floor Brick Work	Done	100%
Ground Floor Internal Plaster	Done	100%
Column 1st Floor To 2nd Floor	Done	100%
2nd Floor Slab Casting	Done	100%
1st Floor Brick Work	Done	100%
1st Floor Internal Plaster	Done	100%
Column 2nd Floor To 3rd Floor	Done	100%
3rd Floor Slab Casting	Done	100%
2nd Floor Brick Work	Done	100%
2nd Floor Internal Plaster	Done	100%
Column 3rd Floor To 4th Floor	Done	100%
4th Floor Slab Casting	Done	100%
3rd Floor Brick Work	Done	100%
3rd Floor Internal Plaster	Done	100%
Column 4th Floor To 5th Floor	Done	100%
5th Floor Slab Casting	Done	100%
4th Floor Brick Work	Done	100%
4th Floor Internal Plaster	Done	100%
Column 5th Floor To Roof	Done	100%
Roof Slab Casting	Done	100%
5th Floor Brick Work	Done	100%
5th Floor Internal Plaster	Done	100%
Column Roof To Lift Motor Room Level	Done	100%
Lift Motor Room Slab Casting	Done	100%
Roof Brick Work	Done	100%
Roof Internal Plaster	Done	100%
Staircase Brickwork	Done	100%
Staircase Plaster	Done	100%
External Plaster	Done	100%

Devashilpi-Ekam (Phase-1) Tower-3, Work Progress As On 30-09-2025

TASK	STATUS	COMPLETION %
Putty Work		
Ground Floor	Done	100%
1st Floor	Done	100%
2nd Floor	Done	100%
3rd Floor	Done	100%
4th Floor	Done	100%
5th Floor	Done	100%
Roof	Done	100%
Painting Work-Internal & External		
Internal Primer Work		
Ground Floor	Done	100%
1st Floor	Done	100%
2nd Floor	Done	100%
3rd Floor	Done	100%
4th Floor	Done	100%
5th Floor	Done	100%
Roof	Done	100%
External Plaster Coat	Done	100%
External Plaster Coat	Done	100%
External Primer	Done	100%
External Paint ##	In progress	10%
Note: ## Exterior painting work is on hold due to continuous rain and unfavorable weather conditions.		
Plumbing Work & Sanitary Fittings		
Ground Floor Internal	Done	100%
Ground Floor External	Done	100%
1st Floor	Done	100%
2nd Floor	Done	100%
3rd Floor	Done	100%
4th Floor	Done	100%
5th Floor	Done	100%
Roof	Done	100%
Building Outside Vertical	Done	100%
Electrical Work		
Ground Floor	Done	100%
1st Floor	Done	100%
2nd Floor	Done	100%
3rd Floor	Done	100%
4th Floor	Done	100%
5th Floor	Done	100%
Roof	Done	100%
Lift Electrical Work	Done	100%

Devashilpi-Ekam (Phase-1)Tower-3, Work Progress As On 30-09-2025

TASK	STATUS	COMPLETION %
Flooring Work		
1st Floor	Done	100%
2nd Floor	Done	100%
3rd Floor	Done	100%
4th Floor	Done	100%
5th Floor	Done	100%
Roof	Done	100%
Staircase	Done	100%
Roof	Done	100%
MS Grill in Window & Railing in Balcony		
Ground Floor	Done	100%
1st Floor	Done	100%
2nd Floor	Done	100%
3rd Floor	Done	100%
4th Floor	Done	100%
5th Floor	Done	100%
Roof	Done	100%
Aluminium Window & Balcony Sliding Door		
Ground Floor	Done	100%
1st Floor	Done	100%
2nd Floor	Done	100%
3rd Floor	Done	100%
4th Floor	Done	100%
5th Floor	Done	100%
Roof	Done	100%
Wooden/PVC/Iron Door Frame & Door Fitting Work		
Ground Floor	Done	100%
1st Floor	Done	100%
2nd Floor	Done	100%
3rd Floor	Done	100%
4th Floor	Done	100%
5th Floor	Done	100%
Roof	Done	100%
Staircase Marble/Granite/Tiles Work & Railing Work		
1st Floor	Done	100%
2nd Floor	Done	100%
3rd Floor	Done	100%
4th Floor	Done	100%
5th Floor	Done	100%
Roof	Done	100%