




# **Bl-1- 1st Floor**

A long, narrow hallway with peeling paint on the walls and a white bag on the floor. The hallway leads to a bright light at the end. The floor is made of large, dark tiles. The walls are a light color with significant peeling and discoloration. A small window is visible on the left wall. A white bag is lying on the floor near the left wall. The hallway is very long and narrow, with a series of doorways and openings along the walls. The lighting is dim, with the brightest light coming from the end of the hallway.

# **Bl-1- 2nd Floor**



**BI-1/3rd Floor**



**Bl-1/4th Floor**

A photograph of a long, narrow hallway. The walls are white but show significant signs of wear, including peeling paint and stains. The floor is dark and reflective. A small window is visible on the left wall. The hallway leads to a bright light source at the far end, creating a strong perspective.

**Bl-1/5th Floor**

A photograph of a long, narrow hallway with peeling paint on the walls and a window on the left side. The hallway leads to a bright light at the end. A white rounded rectangle is overlaid on the center of the image containing the text "Bl-1/6th Floor".

**Bl-1/6th Floor**



**Bl-1/7th Floor**

A long, narrow hallway with peeling paint on the walls and a window on the left side. The floor is dark and reflective. The hallway leads to a bright area at the end.

**Bl-1/8th Floor**